

ACCESSORI e parti staccate per ganasce / ACCESSORIES and loose parts for jaws

Tipo (grandezza) morsa / Vise (type) size

1 2 3 4 5 6


Art. 132

Prolunga per ganasce mobile. Larghezza normale
Extension for movable jaw. Normal width

NO StandardFLEX

Cod. 2.13.21000 2.13.22000 2.13.23000 2.13.24000 2.13.25000 2.13.26000

Art. 134

Prolunga per ganasce mobile. Super ridotta
Extension for movable jaw. Super narrow


Cod. 2.13.41000 2.13.42000 2.13.43000 2.13.44000 2.13.45000 2.13.46000

Art. 133

Prolunga per ganasce fissa. Larghezza normale
Extension for fixed jaw. Normal width


Cod. 2.13.31000 2.13.32000 2.13.33000 2.13.34000 2.13.35000 2.13.36000

Art. 135

Prolunga per ganasce fissa. Ridotta e super ridotta
Extension for fixed jaw. Narrow and super narrow

NO StandardFLEX

Cod. 2.13.51000 2.13.52000 2.13.53000 2.13.54000 2.13.55000 2.13.56000

Art. 260

Segmento oscillante per ganasce mobili. **Art. 190 - 191**
Floating segment for movable jaws. **Art. 190 - 191**


Cod. 1.26.01000 1.26.02000 1.26.03000 1.26.04000 1.26.05000 1.26.06000

Art. 362

Molla per piastre ganasce
Spring for jaw plates


Cod. 0.70.10000 0.70.20000 0.70.30000 0.70.40000 0.70.50000 0.70.60000

Art. 380

Vite TCEI fissaggio corpo ganasce fissa
Hex socket and screw for fixed jaw body

Cod. 0.01.11030 0.01.10865 0.01.11450 0.01.11660 0.01.12065 0.01.12080

Art. 381

Vite TCEI fissaggio piastra ganasce fissa
Hex socket screw for fixed plate


Cod. 0.01.10565 0.01.11240 0.01.11451 0.01.11661 0.01.12066 0.01.12081

Art. 382

Vite TCEI fissaggio piastra ganasce mobile
Hex socket and screw for movable jaw plate

Cod. 0.01.10525 0.01.10830 0.01.10840 0.01.10845 0.01.11050 0.01.11065

Art. 383

Vite TCEI fissaggio piastra ganasce fissa doppia
Hex socket and screw for double fixed jaw

Cod. 0.01.10520 0.01.10620 0.01.10820 0.01.11820 0.01.11020 0.01.11020

Art. 384

Vite TCEI per arresto laterale
Hex socket and screw for workstop

Cod. 0.06.11100 0.06.22200 0.06.33300 0.06.44400 0.06.55500 0.06.66600

Art. 431

Rondella per arresto laterale
Washer for workstop



Cod. 2.43.11000 2.43.12000 2.43.13000 2.43.14000 2.43.15000 2.43.16000


Art. 440

Dado per arresto laterale
Nut for workstop


Cod. 2.44.01000 2.44.02000 2.44.03000 2.44.04000 2.44.05000 2.44.06000

Art. 570

Puntale sferico liscio
Smooth spherical point

Art. 570S

Puntale sferico zigrinato
Serrated spherical point


Cod. 1.57.01000 1.57.02000 1.57.03000 1.57.04000 1.57.05000 1.57.06000

Cod. 1.57.0S100 1.57.0S200 1.57.0S300 1.57.0S400 1.57.0S500 1.57.0S600