

Tipo (grandezza) morsa / Vise (type) size		1	2	3	
<b>Art. 608A</b>	Ganascia fissa con gradino / Fixed jaw with step		Cod. 6.60.8A100	6.60.8A200	6.60.8A300
<b>Art. 613A</b>	Ganascia mobile / Movable jaw		Cod. 6.61.3A100	6.61.3A200	6.61.3A300
<b>Art. 613B</b>	Cuneo di spinta / Clamping wedge		Cod. 6.61.3B100	6.61.3B200	6.61.3B300
<b>Art. 613C</b>	Dado a "T" / "T" nut		Cod. 6.61.3C100	6.61.3C200	6.61.3C300
<b>Art. 613D</b>	Vite TCEI / Hex socket head screw		Cod. 6.61.3D100	6.61.3D200	6.61.3D300
<b>Art. 613E</b>	Grano / Set screw		Cod. 6.61.3E100	6.61.3E200	6.61.3E300
<b>Art. 613F</b>	Molla / Spring		Cod. 6.61.3F100	6.61.3F200	6.61.3F300
<b>Art. 615A</b>	Cuneo di posizionamento liscio maggiorato Positioning wedge smooth (increased with respect to stand dimension)		Cod. 6.61.5A100	6.61.5A200	6.61.5A300
<b>Art. 615AS</b>	Cuneo di posizionamento zigrinato maggiorato Positioning wedge serrated (increased with respect to stand dimension)		Cod. 6.61.5AS10	6.61.5AS20	6.61.5AS30
<b>Art. 615I</b>	Cuneo di posizionamento dolce maggiorato Positioning wedge soft (increased with respect to stand dimension)		Cod. 6.61.5I100	6.61.5I200	6.61.5I300
<b>Art. 615L</b>	Cuneo di posizionamento a gradino maggiorato Positioning wedge with stop (increased with respect to stand dimension)		Cod. 6.61.5L100	6.61.5L200	6.61.5L300
<b>Art. 615C</b>	Vite TCEI fissaggio ganascia fissa Hex socket head screw for fixed jaw		Cod. 6.61.5C100	6.61.5C200	6.61.5C300
<b>Art. 615E</b>	Vite TCEI TCEI screw		Cod. 6.61.5E100	6.61.5E200	6.61.5E300

