

WIRELESS DATA TRANSFER SYSTEM

Code	Description	Applicable products
7306-2	receiver	USB and RS232 connection ports, strong transmission signal, the maximum distance is 100m
7306-1	mini receiver	USB connection port, for short distance (within 20m) or barrier-free area
7306-20	transmitter	digital calipers, digital depth gages and digital height gages (not for 1103, 1150)
7306-30	transmitter	digital micrometers, digital three point internal micrometers (not for 3631, 3632, 3108, 3109, 3635)
7306-30A	transmitter	digital micrometers, digital three point internal micrometers (not for 3631, 3632, 3108, 3109, 3635)
7306-40	transmitter	digital indicators digital protractors

DATA COLLECTION:

- 1) Single collection: press the read button once to collect the reading from measuring tool once.
- 2) Multi collection: press the read button once to start collecting readings from measuring tools continuously, press the button again to stop collecting. Total collection times and interval time can be adjusted.

DISPLAY: data can be input to Excel as keyboard signal.

measuring tools code A, B, C

All data are displayed in the same column. Each measuring tool can be coded such as A, B, C, etc.



receiver
7306-2



transmitter
7306-20



VIDEO



protecting cap
(optional)
code 7306-CAP



software CD
(included)



read
button

- **CONNECTION:** one receiver can be connected to 30 transmitters.



7302-SPC5A 7302-SPC5B 7302-SPC2A 7302-SPC6 7302-SPC3A 7302-SPC4



USB DATA OUTPUT CABLES



VIDEO



7304-2

Code	Description	Remark
7302-SPC5A	cable (length 2.5m)	for digital calipers and digital depth gages (not for 1103)
7302-SPC5B	cable (length 2.5m)	for digital calipers and digital depth gages (not for 1103)
7302-SPC2A	cable (length 2.5m)	for digital micrometers (not for 3631, 3632, 3108, 3109, 3635)
7302-SPC6	cable (length 2.5m)	for digital micrometers (not for 3631, 3632, 3108, 3109, 3635)
7302-SPC3A	cable (length 2.5m)	for digital indicators digital protractors
7302-SPC4	cable (length 2.5m)	for digital calipers 1103 series (for 1103 only)
7304-2	foot switch with cable (length 1.5m)	optional

- Connect to USB port of computer
- Without software, data can be input as keyboard signal to Excel, Word, etc.
- Press the red button or foot switch (optional) to input data

